

## Proposed Code Change State Form 41186R

RETURN TO: INDIANA DEPARTMENT OF HOMELAND SECURITY CODE SERVICES SECTION 302 W. Washington Street Room W246

Indianapolis, IN 46204

INSTRUCTIONS:

Only TYPED copy accepted.

(KEY - Dashed line through material to be deleted, underline material to be added)

FOR OFFICE USE ONLY

Received 1/19/10

Code 32.05-09R

Use second sheet for any material requiring more space.					
Code Title	Edition				
2009 Indiana Residential Code	First				
Section number and title	Page				
R311.3.2 Floor elevations for other exterior d					
Proponent					
Phil Gettum	Indiana Builder's Association				
Address	rs ·				
4984 W. Smith Valley Rd, Greenwood, In	317-888-5681				
PROPOSED CODE CHANGE (Check One)					
Change to read as follows X Add to read as follows De	elete and substitute as follows	Delete without substitution			
Add exception #2 to read as follows:					
Add exception #2 to read as follows:					
<b>Exception #2:</b> in retrofit situations, the maximum height below the top of the threshold					
of a sliding glass door to the landing or the first tread is not to exceed 8 3/4".					
grade door to the landing of the first fload to flot to exceed a 6/4.					
REASON AND FI	SCAL IMPACT				
		1/8") than a standard			
Sliding glass doors are often now made with a taller threshold (2 $1/8$ ") than a standard exterior swing door (1 $1/2$ " – 1 $3/4$ "). Permitting the extra $1/2$ " in height for this					
secondary, none required, exterior door allows a sliding glass door to replace a					
standard swing door that was installed per code. This situation is further impacted by					
the fact that the normal pedestrian traffic thru a sliding glass door does not encourage					
one to step up on the threshold but to step over it. Because it is not the "required"					
egress doorway, the use of this passage way would normally be limited and would not					
effect emergency egress and would normally be used by occupants who would be					
accustomed to this condition. Cost savings could be several thousand dollars saved by					
not having to reconfigure decks, steps or landings when replacing a door.					
REVIEW RECOMMENDATION					
Approve					
Disapprove					
Approve as amended					
Further Study					